

## JA: Vehicle Speed Sensor

[← JA: Introduction](#)

### JA1 DTC P0500: CHECK CONTINUITY OF VSS HARNESS CIRCUITS

- Diagnostic Trouble Code (DTC) P0500 indicates that a VSS malfunction has been detected.

**Note:** Delayed engagement or no vehicle movement may be caused by a transmission concern. Harsh shifts and/or erratic speedometer may be caused by a failed speedometer or an open or intermittent ground within the instrument panel on vehicles with electronic readout.

- Possible causes:
  - Open in VSS (+)/VSS (-) harness circuit.
  - Short to GND or SIG RTN in VSS (+)/VSS (-) harness circuit.
  - Short to PWR in VSS (+)/VSS (-) harness circuit.
  - Damaged VSS.
  - Damaged PCM.
- Key off.
- Disconnect PCM. Inspect for damaged or pushed out pins, corrosion, loose wires, etc. Service as necessary.
- Install breakout box, PCM disconnected.
- Disconnect VSS.
- Measure resistance between Test Pin 58 [VSS (+)] at the breakout box and VSS (+) circuit at the VSS vehicle harness connector.
- Measure resistance between Test Pin 33 [VSS (-)] at the breakout box and VSS (-) circuit at the VSS vehicle harness connector.

Is each resistance less than 5.0 ohms?

| Yes                         | No  |
|-----------------------------|---|
| GO to <a href="#">JA2</a> . | SERVICE open in harness circuit. REMOVE breakout box. RECONNECT all components. RESTORE vehicle. CLEAR DTCs and RETEST. |

### JA2 CHECK VSS HARNESS CIRCUITS FOR SHORTS TO GROUND, SIG RTN AND POWER

- Key off.
- VSS disconnected.
- Breakout box installed, PCM disconnected.
- Measure resistance between Test Pin 58 [VSS (+)] and Test Pins 24, 61, 76, and 103 (PWR GND).
- Measure resistance between Test Pin 58 [VSS (+)] and Test Pin 33 [VSS (-)].
- Measure resistance between Test Pin 58 [VSS (+)] and Test Pins 91 (SIG RTN).
- Measure resistance between Test Pin 58 [VSS (+)] and Test Pin 71 (VPWR).
- Measure resistance between Test Pins 33 [VSS (-)] and 71 (VPWR) at the breakout box.

Is each resistance greater than 500 ohms?

| Yes                       | No  |
|---------------------------|---|
| GO to <a href="#">JA3</a> | SERVICE short circuit. REMOVE the breakout box. RECONNECT all components. RESTORE vehicle. CLEAR DTCs and RETEST. |

**JA3 CHECK VSS RESISTANCE**

- Key off.
- VSS disconnected.
- Measure the resistance of the VSS.

**Is resistance between 190 and 250 ohms?**

| Yes  | No   |
|--|--|
| REMOVE the breakout box. REPLACE the PCM. RECONNECT the VSS. RESTORE vehicle. CLEAR DTCs and RETEST. | REPLACE the VSS. REMOVE breakout box. RECONNECT the PCM. RESTORE vehicle. CLEAR DTCs and RETEST. |

**JA4 DTC P0500: CHECK VSS SIGNAL OUTPUT TO POWERTRAIN CONTROL MODULE (PCM)**

- Diagnostic Trouble Code (DTC) P0500 indicates that a VSS malfunction has been detected.

**Note:** Delayed engagement or no vehicle movement may be caused by a transmission concern. Harsh shifts and/or erratic speedometer may be caused by a failed speedometer or an open or intermittent ground within the instrument panel on vehicles with electronic readout.

- Possible causes:
  - Open in VSS, VPWR, PWR GND harness circuit.
  - Short to GND in VSS harness circuit.
  - Short to PWR in VSS harness circuit.
  - Damaged VSS.
  - Damaged PCM.
- Key off.
- Disconnect Powertrain Control Module (PCM). Inspect for damaged or pushed out pins, corrosion, loose wires, etc. Service as necessary.
- Install scan tool and set to frequency count with an amplitude of 2 volts.
- From a stop, accelerate to 48 km/h (30 mph).
- The frequency reading should increase to a reading between 45-85 HTZ.

**Is the VSS output within specification?**

| Yes                         | No   |
|-----------------------------|--|
| GO to <a href="#">JA5</a> . | REPLACE the VSS. RESTORE vehicle. CLEAR DTCs and RETEST. |

**JA5 CHECK THE BATTERY VOLTAGE TO VSS**

- Key off.
- Disconnect VSS.
- Key on.
- Measure voltage at VPWR pin to GND pin at the VSS vehicle harness connector.

**Is the voltage greater than 10.5 volts?**

| Yes | No |
|-----|----|
|     |    |

GO to [JA6](#) .GO to [JA9](#) .**JA6 CHECK VSS CIRCUIT SHORT TO POWER**

- VSS disconnected.
- Key on, PCM disconnected.
- Measure voltage between Test Pin 58 and Test Pin 103 at the breakout box.

**Is the voltage less than 1.0 volt?**

| Yes                         | No   |
|-----------------------------|--|
| GO to <a href="#">JA7</a> . | SERVICE short to power. REMOVE breakout box. RECONNECT all components. RESTORE vehicle. CLEAR DTCs and RETEST. |

**JA7 CHECK VSS CIRCUIT SHORT TO GROUND**

- Key off.
- VSS disconnected.
- Measure resistance between Test Pin 58 and Test Pin 103 at breakout box.

**Is resistance greater than 3,000 ohms?**

| Yes                         | No  |
|-----------------------------|---|
| GO to <a href="#">JA8</a> . | SERVICE short to ground. REMOVE breakout box. RECONNECT all components. RESTORE vehicle. CLEAR DTCs and RETEST. |

**JA8 CHECK CONTINUITY OF VSS HARNESS CIRCUIT**

- Key off, VSS disconnected.
- PCM disconnected.
- Measure resistance between Test Pin 58 at the breakout box and the VSS circuit at the VSS vehicle harness connector.

**Is resistance less than 5.0 ohms?**

| Yes   | No   |
|---|--|
| REPLACE VSS. REMOVE the breakout box. RECONNECT all components. RESTORE vehicle. CLEAR DTCs and RETEST. | SERVICE open circuit. REMOVE the breakout box. RECONNECT all components. RESTORE vehicle. CLEAR DTCs and RETEST. |

**JA9 CHECK CONTINUITY OF VSS GROUND HARNESS CIRCUIT**

- Key off, VSS disconnected.
- PCM disconnected.
- Measure resistance between GND Pin at the VSS vehicle harness connector and chassis ground.

**Is resistance less than 5.0 ohms?**

| Yes  | No   |
|--|--|
| SERVICE open VPWR to VSS. REMOVE breakout box. RECONNECT all components. RESTORE vehicle. CLEAR DTCs and RETEST. | SERVICE open VSS GND circuit. REMOVE breakout box. RECONNECT all components. RESTORE vehicle. CLEAR DTCs and RETEST. |

**JA10 KOER DTC P1501: CHECK PCM VSS PID FOR INPUT SIGNAL**

- Diagnostic Trouble Code (DTC) P1501 indicates the VSS input signal is out of Self Test range.

**Note:** When the PCM detects a VSS input signal any time during KOER testing, a DTC P1501 will be set and the testing will abort.

- Possible causes:
  - Noisy VSS input signal from RFI/EMI external sources such as ignition wires or charging circuit as examples.
- Start the engine and idle in neutral.
- Access the VSS PID with a scan tool and observe for vehicle speed input to the PCM.
- Increase the engine speed, not greater than 2000 rpm, several times while observing the VSS PID.

**Is the reading on the VSS PID less than 3 mph (5 km/h)?**

| Yes   | No                           |
|---|------------------------------|
| Unable to duplicate or identify a fault at this time. RESTORE vehicle. CLEAR DTCs and RETEST. | GO to <a href="#">JA13</a> . |

**JA11 DTC P0502: INSPECT VSS AND CIRCUIT FOR AN INTERMITTENT**

- Continuous Memory DTC P0502 indicates poor VSS performance.
- Possible causes:
  - Noisy VSS input signal from RFI/EMI external sources such as ignition wires or charging circuit as examples.
  - Damaged VSS or driven gears.
  - Damaged wiring harness or connectors.
- Check for harness intermittents.
  - Pins properly seated in connector shell; wiring properly crimped; no corrosion; sensor securely mounted.

**Are there any indications of harness intermittents?**

| Yes   | No                           |
|---|------------------------------|
| SERVICE as necessary. RESTORE vehicle. CLEAR DTCs and RETEST. | GO to <a href="#">JA12</a> . |

**JA12 CHECK PCM VSS PID FOR INPUT SIGNAL**

- Access the VSS PID with a scan tool.
- Drive the vehicle at several steady state speeds above and below 50 km/h (30 mph).
- During each steady state speed observe the VSS PID for variations of (+) or (-) 8 km/h (5 mph) for greater than 10 seconds.

**Note:** For scan tools which have Data Record feature, recording data for playback may help in identifying variations easier.

**Were there any indications of a noisy or intermittent signal with the VSS PID?**

| Yes                          | No  |
|------------------------------|---|
| GO to <a href="#">JA13</a> . | Unable to duplicate or identify a fault at this time. DTC P0502 may have been set from sources external to the vehicle. SERVICE any other DTCs. RESTORE vehicle. CLEAR DTCs and RETEST. |

**JA13 CHECK VSS HARNESS ROUTING**

- Check VSS harness routing.
  - Verify that the harness is not routed adjacent to high current wires, i.e. ignition wires or alternator wiring.
  - Verify VSS harness is shielded and grounded, if applicable.
  - Check continuity of the VSS harness; GO to [JA1](#) .

**Are any problems evident?**

| Yes   | No   |
|---|--|
| SERVICE as necessary. RESTORE vehicle. CLEAR DTCs and RETEST. | Unable to duplicate or identify a fault at this time. RERUN <a href="#">Quick Test</a> . |

---