

---

**MD: PCM-ROM Failure**

---

**MD1 DIAGNOSTIC TROUBLE CODE (DTC) P0605**

- DTC P0605 is set when a read only memory (ROM) failure is detected in the powertrain control module (PCM).
- Possible causes:
  - internal PCM failure
  - incorrect PCM calibration
- Perform the Key On Engine Off (KOEO) On-Demand Self-Test.

**Is DTC P0605 present?**

Yes	No
REFLASH the PCM. CLEAR the DTCs and REPEAT the self-test. If DTC P0605 is present again, INSTALL a new PCM. CLEAR the DTCs and REPEAT the self-test.	System OK. CLEAR the DTCs and REPEAT the self-test.

---