

**AG: PCM-ROM Failure**

---

**AG1 DIAGNOSTIC TROUBLE CODE (DTC) P0605: PCM ROM FAILURE**

- DTC P0605 exists only when there has been an internal failure of the powertrain control module (PCM).
- Rerun Scan Tool Diagnostic Test.

**Is DTC P0605 retrieved?**

Yes	No
REPLACE PCM.	System OK. RERUN Scan Tool Diagnostic Test to see if there are any other stored DTCs.

---